Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number Database(s) EPA ID Number

CJ421 VAULT VS 7238 NY Spills S107787670 NNW SOUTH SIDE AVE X NEAR STILLWELL AVE N/A

NNW SOUTH SIDE AVE X NEAR STILLWELL AVE 1/2-1 BROOKLYN, NY

0.667 mi.

3520 ft. Site 3 of 3 in cluster CJ

Relative: SPILLS:
Higher Name: VAULT VS 7238

Actual: Address: SOUTH SIDE AVE X NEAR STILLWELL AVE

8 ft. City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0600983 / 2006-05-15

 Facility ID:
 0600983

 Facility Type:
 ER

 DER Facility ID:
 313301

 Site ID:
 363108

DEC Region: 2

Spill Cause: Equipment Failure

Spill Class: C4
SWIS: 2401
Spill Date: 2006-04-25
Investigator: GDBREEN
Referred To: Not reported
Reported to Dept: 2006-04-25
CID: 408

Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Responsible Party

Spill Notifier: Responsible
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

Date Entered In Computer: 2006-04-25 Spill Record Last Update: 2006-06-12 Spiller Name: ERT DESK

Spiller Company: CON EDISON VAULT VS 7238

Spiller Address: SOUTH SIDE AVE X

Spiller Company: 999
Contact Name: ERT DESK'

DEC Memo: "05/15/06 - See e-docs for Con Ed report detailing cleanup and

closure. 05/15/06 - See e-docs for Con Ed report detailing cleanup

and closure. 163944. see eDocs"

Remarks: "THERE IS A TRANSFORMER INVOLVED BUT IS NOT LEAKING AT THIS AT THIS

TIME, PRODUCT IS ON 1500 GALLONS OF WATER, CONTAINED IN THE STRUCTURE AND CLEAN UP IS PENDING LAB RESULTS. 446 FT NORTH OF STILLWELL AVE.

163944"

All Materials:

363108 Site ID: Operable Unit ID: 1121175 Operable Unit: 01 Material ID: 2110667 Material Code: 0541A Material Name: dielectric fluid Case No.: Not reported Material FA: Petroleum Quantity: 7.00 Units: G .00 Recovered:

Map ID		MAP FINDINGS		
Direction		4		
Distance				EDR ID Number
Elevation	Site		Database(s)	EPA ID Number

Oxygenate: Not reported